





The diagram shows a synchronous motor. On the left, a field winding is represented by a circle with a cross, connected to a DC source 'x'. This winding is mounted on a rotor, which is shown as a circle with a cross. The rotor is connected to a stator winding, represented by a circle with a dot. The stator winding is connected to an AC source, indicated by a sine wave symbol.

[illegible]